

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated:

It is certified that the existing building Railway Higher Secondary School, Maligaon (name of the building or premises) at Maligaon GHY-781011, Dist:- Kamrup(M), Assam (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+2	Auditorium				

The building is owned/occupied by Railway Higher Secondary School, Maligaon (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Indian Railway (Name of Department/ Govt.) on 15-03-2024 (date of inspection) in the presence of SSB/WHQ/MLG & School Principal (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 15-03-2024 for a period of 01 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Need repairing for East side portion of Main Block (G+2).

2.

3.

4.

Issued on 21-03-2024 at Gunabhati by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : _____

Name : ANURAG

Designation : SEN/MLG

Name & Address of Department/ Office: O/o Dy CE/Estt